




*FIG. 1A*



*FIG. 1B*




*FIG. 2*



*FIG. 3*  
*(Prior Art)*



With no filler




At speed 15000 rpm-maximum stress in iron 5000 MPa

BEST AVAILABLE COPY

FIG. 5

With epoxy resin filler



At speed 15000 rpm—maximum stress in iron 286 MPa

BEST AVAILABLE COPY

FIG. 6